



Integrated Safety Management at the Activity Level

Working Safely and Efficiently

July 27 and July 28, 1999

Doubletree Inn

Pasco, Washington

Workshop Agenda

Tuesday, July 27, 1999

- | | |
|------------------|--|
| 6:30 - 7:30 a.m. | Check In/Registration/Poster Session |
| 7:30 - 7:35 a.m. | Introductions/ Organization-Preview of Workshop
Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP |
| 7:35 - 8:05 a.m. | Welcoming Messages
Keith A. Klein, Manager, DOE Richland Operations Office
Richard T. French, Manager, DOE Office of River Protection
Dave Van Leuven, Executive Vice President, Fluor Daniel Hanford
Jeff Smith, Deputy Director of Laboratory Operations, PNNL, Energy Division
Steve Liedle, President, Bechtel Hanford, Inc.
John Jeskey, HAMTC Safety Representative |
| 8:05 - 8:20 a.m. | Keynote Address
Joe DiNunno, DNFSB Member |
| 8:20 - 8:30 a.m. | Special Message - Verification of ISMS Implementation
Ted Wyka - DOE Safety Management Implementation Team (SMIT) Director |
| 8:30 - 8:45 a.m. | Video Presentation - "ISMS - Bringing It All Together" |
| 8:45 - 9:00 a.m. | Break |
| 9:00 - 9:15 a.m. | Workshop Breakout Sessions Overview - (Workshop Themes)
Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP

Jim Klos, SNF ISM Coordinator (DE&S)
First Line Supervisor and Management Commitment
Bill Dixon, RPP ES&H (LMHC)
Worker Involvement |

Dick Mitchell , DynCorp Infrastructure ISM Coordinator (DYN)

Work Control and Job Hazard Analysis

Lou Simmons, B&WHC ISM Coordinator (B&WHC)

Activity Level Feed Back, Improvement, and Communication

9:15 – 10:15 a.m.

PHMC Project Leadership Panel - (ISM Core Functions)

Moderator:

Gerald B. Griffin, Project Manager, B&WHC/FDH-ISM

Edward S. Aromi, President, Waste Management Hanford

Define Scope of Work

Mary P. (Fran) DeLozier, President Lockheed Martin Hanford Company

Identify Hazards and ES&H Requirements

Arthur Clark, President B&W Hanford Company

Analyze Hazards and Implement Controls

Raymond G. Jones, Executive VP Fluor Daniel Company

Perform Work Within Controls

Robert S. Frix, President DynCorp Services

Provide Feedback and Continuous Improvement

10:15 - 10:30 a.m.

Break – Setup for Breakout Sessions

10:30 – 11:15 a.m.

"A" Breakout Sessions (See attached schedule)

11:15 – 11:30 a.m.

Break

11:30 – 12:15 p.m.

"B" Breakout Sessions (See attached schedule)

12:15 – 1:15 p.m.

Lunch (on your own)

1:15 – 2:00 p.m.

"C" Breakout Sessions (See attached schedule)

2:00 – 2:15 p.m.

Break

2:15 -3:00 p.m.

"D" Breakout Sessions (See attached schedule)

3:00 – 3:15 p.m.

Break

3:15 – 4:00 p.m.

"E" Breakout Sessions (See attached schedule)

4:00 – 4:15 p.m.

Break

4:15 – 4:20 p.m.

Closing Remarks

Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP

4:25 p.m.

Door Prize Award

4:30 p.m.

Adjourn



Integrated Safety Management at the Activity Level

Working Safely and Efficiently

July 27 and July 28, 1999

Doubletree Inn

Pasco, Washington

Workshop Agenda

Wednesday, July 28, 1999

- 6:30 - 7:30 a.m. **Check In/Registration/Poster Session**
- 7:30 - 7:35 a.m. **Introductions/ Organization-Preview of Workshop**
Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP
- 7:35 - 8:05 a.m. **Welcoming Messages**
Keith A. Klein, Manager, DOE Richland Operations Office
Richard T. French, Manager, DOE Office of River Protection
Dave Van Leuven, Executive Vice President, Fluor Daniel Hanford
Jeff Smith, Deputy Director of Laboratory Operations, PNNL, Energy Division
Steve Liedle, President, Bechtel Hanford, Inc.
John Jeskey, HAMTC Safety Representative
- 8:05 - 8:10 a.m. **Keynote Addresses**
Richard Terrell or Paula White, OSHA
- 8:10 - 8:20 a.m. Richard Kiy, DOE EH-1
- 8:20 - 8:30 a.m. **Special Message** - Verification of ISMS Implementation
Ted Wyka - DOE Safety Management Implementation Team (SMIT)
- 8:30 - 8:45 a.m. Video Presentation - "ISMS - Bringing It All Together"
- 8:45 - 9:00 a.m. Break
- 9:00 - 9:15 a.m. **Workshop Breakout Sessions Overview - (Workshop Themes)**
Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP
- Jim Klos, SNF ISM Coordinator (DE&S)
- First Line Supervisor and Management Commitment**
Bill Dixon, RPP ES&H (LMHC)
- Worker Involvement**

Dick Mitchell , DynCorp Infrastructure ISM Coordinator (DYN)

Work Control and Job Hazard Analysis

Lou Simmons, B&WHC ISM Coordinator (B&WHC)

Activity Level Feed Back, Improvement, and Communication

9:15 – 10:15 a.m.

PHMC Project Leadership Panel - (ISM Core Functions)

Moderator:

Gerald B. Griffin, Project Manager, B&WHC/FDH-ISM

Edward S. Aromi, President, Waste Management Hanford

Define Scope of Work

Mary P. (Fran) DeLozier, President Lockheed Martin Hanford Company

Identify Hazards and ES&H Requirements

Arthur Clark, President B&W Hanford Company

Analyze Hazards and Implement Controls

Raymond G. Jones, Executive VP Fluor Daniel Company

Perform Work Within Controls

Robert S. Frix, President DynCorp Services

Provide Feedback and Continuous Improvement

10:15 - 10:30 a.m.

Break – Setup for Breakout Sessions

10:30 – 11:15 a.m.

"A" Breakout Sessions (See attached schedule)

11:15 – 11:30 a.m.

Break

11:30 – 12:15 p.m.

"B" Breakout Sessions (See attached schedule)

12:15 – 1:15 p.m.

Lunch (on your own)

1:15 – 2:00 p.m.

"C" Breakout Sessions (See attached schedule)

2:00 – 2:15 p.m.

Break

2:15 -3:00 p.m.

"D" Breakout Sessions (See attached schedule)

3:00 – 3:15 p.m.

Break

3:15 – 4:00 p.m.

"E" Breakout Sessions (See attached schedule)

4:00 – 4:15 p.m.

Break

4:15 – 4:20 p.m.

Closing Remarks

Jim Schildknecht, Project Manager, FDH Conduct of Ops/ISM/EWP

4:25 p.m.

Door Prize Award

4:30 p.m.

Adjourn